



### **GTR Lighting Knowledgebase Article: 2008 Chevy Trailblazer HID Kit Install**

When installing an HID conversion kit into a 2008 Chevy Trailblazer (SS and regular models) you may encounter random flickering issues on the low beam. For some reason when the ignition is turned off the low beam HID bulb will flash.

Also, sometimes while driving the low beam HID will flicker and create a strobing effect.

What we've even seen is when an aftermarket remote start has been installed in the truck and the "illuminated entry" function is enabled, the flicker/strobe effect takes place then as well. Illuminated entry is the name for the feature that keeps the headlights on after you turn off your vehicle and you are getting out and walking towards your house.

#### **THE FIX:**

What you need to do to solve this problem or avoid it all together is to install a single beam relay harness and one warning canceller module. Install the warning canceller module between the factory 9006 low beam harness and the new relay harness. This will trick the vehicle into thinking a factory bulb is in place and allow you to run an HID conversion kit without flickering.

